

C-SERIES COMPARISON CHART



	CSX	CSF	CSD	CSS
CARTON SPEED	Up to 12 Cartons/min.	Up to 15 Cartons/min.	Up to 20 Cartons/min.	Up to 30 Cartons/min.
POWER REQUIREMENTS	110 Volts 60 HZ	208 Volts 3 Phase	208 Volts 3 Phase	208 Volts 3 Phase
AIR REQUIREMENTS	100 PSI 12+ SCFM	80 PSI 9 SCFM	80 PSI 5 SCFM	80 PSI 3.5 SCFM
NUMBER OF CARTON SIZES	2 - 10 Carton Sizes	10+ Carton Sizes	10+ Carton Sizes	10+ Carton Sizes
AMOUNT OF SERVO MOTORS	×	1 Servo Motor	2 Servo Motor	5 Servo Motor
HUMAN MACHINE INTERFACE	×	✓	✓	✓
COST	\$	\$\$	\$\$\$	\$\$\$\$