



RS22 SPARE PARTS KIT 2" RANDOM SIDEDRIVE CARTON SEALER







TOP & BOTTOM SEAL

OPERATOR REQUIRED

RANDOM CARTONS

2" Spare Parts Kit Part#: RS22SK

QUANTITY	PART NUMBER	DESCRIPTION
2	27280031	Bearing, Ball 6003zz
2	900600SBAC	Belt, 1860mm X2" Blk
2	27280091	Bearing, Ball 6202zz (Ja)
4	2728102	Bearing, Linear M20
1	10096-1	Spring, Main (Top)
1	10096-2	Spring, Main (Bottom) Chrome
4	10116	Bushing, Bumper M8x7
4	10117	Bumper, Rubber M15x7
2	10122	Blade, Cutter 2"
2	AC231300	Roller, Rubber Front 2"
2	AC232000	Roller, Rubber Rear 2"
2	A1125001	Rubber, Coupler, Blue, (T-hg)
2	A1122000	Coupler, Drive Belt M35x39
2	9510303	Spring, Front Roller
2	9510294	Washer, M21xm10x2 (Plastic)
2	10315	Cushion, Blade 2"
2	9510304	Spring, Blade Guard
4	2706401	Ring, E-clip M3

VERSION 3.1_0419 WWW.BESTPACK.COM

RS22 SPARE PARTS KIT 2" CONTINUED

2" SPARE PARTS KIT PART #: RS22SK

QUANTITY	PART NUMBER	DESCRIPTION
2	9510305	Spring, Support Tape Erect
4	9510300	Spring, Cutter Blade Arm







RS22 SPARE PARTS KIT 3" RANDOM SIDEDRIVE CARTON SEALER







TOP & BOTTOM SEAL

OPERATOR REQUIRED

RANDOM CARTONS

3" Spare Parts Kit Part#: **RS22SK-0**

QUANTITY	PART NUMBER	DESCRIPTION
2	27280031	Bearing, Ball 6003zz
2	900600SBAC	Belt, 1860mm X2" Blk
2	27280091	Bearing, Ball 6202zz (Ja)
4	2728102	Bearing, Linear M20
1	10096-1	Spring, Main (Top)
1	10096-2	Spring, Main (Bottom) Chrome
4	10116	Bushing, Bumper M8x7
4	10117	Bumper, Rubber M15x7
2	10122-0	Blade, Cutter 3"
2	AC331300	Roller, Rubber Front 3"
2	AC332000	Roller, Rubber Rear 3"
2	A1122000	Coupler, Drive Belt M35x39
2	A1125001	Rubber, Coupler, Blue, (T-hg)
2	9510303	Spring, Front Roller
2	9510294	Washer, M21xm10x2 (Plastic)
2	10315-0	Cushion, Blade 3"
2	9510304	Spring, Blade Guard
4	2706401	Ring, E-clip M3

WWW.BESTPACK.COM VERSION 3.1_0419

RS22 SPARE PARTS KIT 3" CONTINUED

3" SPARE PARTS KIT PART #: RS22SK-0

QUANTITY	PART NUMBER	DESCRIPTION
2	9510305	Spring, Support Tape Erect
4	9510300	Spring, Cutter Blade Arm







RS22 SPARE PARTS KIT 6" RANDOM SIDEDRIVE 6" CARTON SEALER







TOP & BOTTOM SEAL

OPERATOR REQUIRED

RANDOM CARTONS

6" Spare Parts Kit Part#: **RS22SK-6**

QUANTITY	PART NUMBER	DESCRIPTION
2	900600SBAC	Belt, 1860mm X2" Blk
2	27280031	Bearing, Ball 6003zz
2	27280091	Bearing, Ball 6202zz (Ja)
4	2728102	Bearing, Linear M20
2	AC631300	Roller, Front Rubber 6"
2	AC633300	Roller, Foam Rear W/ Bushing 6"
2	AC611101	Blade, Cutter 6"
2	10096-1	Spring, Main (Top)
2	10096-2	Spring, Main (Bottom) Chrome
4	10117	Bumper, Rubber M15x7
4	10116	Bushing, Bumper M8x7
2	NT00153	Screw, Socket Pan Hd M5x45
1	AC610400-NT	Shaft, Groove 6" - Dual Springs M8x181
12	AC611900	Spring, Cutter Blade Arm
2	A1122000	Coupler, Drive Belt M35x39
2	A1125001	Rubber, Coupler, Blue, (T-hg)
2	9510303	Spring, Front Roller
2	9510294	Washer, M21xm10x2 (Plastic)

WWW.BESTPACK.COM VERSION 3.1_0419

RS22 SPARE PARTS KIT 6" CONTINUED

6" SPARE PARTS KIT PART #: RS22SK-6

QUANTITY	PART NUMBER	DESCRIPTION
2	AC611720	Cushion, Blade 6"
4	9510304	Spring, Blade Guard
4	2706401	Ring, E-clip M3







RS22 SPARE PARTS KIT 2" STAINLESS RANDOM SIDEDRIVE CARTON SEALER







TOP & BOTTOM SEAL

OPERATOR REQUIRED

RANDOM CARTONS

2" Spare Parts Kit Part#: **RS22STSK**

QUANTITY	PART NUMBER	DESCRIPTION
2	27280045	Bearing, Ball 6003zz St
2	900600SBAC	Belt, 1860mm X2" Blk
2	2728080	Bearing, Linear M20 St
4	2728107	Bearing, Linear M20 St
1	10096-1S	Spring, Main Top Stainless
1	10096-2S	Spring, Main Bottom Stainless
4	10116S	Bushing, Bumper St
4	10117	Bumper, Rubber M15x7
2	10122	Blade, Cutter 2"
2	AC231300	Roller, Rubber Front 2"
2	AC232000	Roller, Rubber Rear 2"
2	A1125001	Rubber, Coupler, Blue, (T-hg)
2	A1122000	Coupler, Drive Belt M35x39
2	9510303S	Spring, Front Roller Stainless
2	9510294	Washer, M21xm10x2 (Plastic)
2	10315	Cushion, Blade 2"
2	9510304S	Ring, Retaining M4 Stainless Steel
4	2706401S	Ring, E-clip M3

WWW.BESTPACK.COM VERSION 3.1_0419

RS22 SPARE PARTS KIT 2" CONTINUED

2" SPARE PARTS KIT PART #: RS22STSK

QUANTITY	PART NUMBER	DESCRIPTION
2	9510305S	Spring, Support St
4	9510300S	Spring, Cutter Blade Arm St

